

TECHNICAL SERVICE BULLETIN

77-C-2

NO.



Austin MG

June, 1977

SUBJECT:

WINDSCREEN GLASS FAILURE

MODELS:

MGB

To eliminate the possibility of windshield glass failure, the glass periphery has been revised at VIN #GHN5UH432905G.

The modified glass, part #HZA-5415 was introduced in conjunction with a new glazing rubber, part # HZA-5414, and may be fitted to earlier windshield frames, utilizing the existing glazing rubber if necessary. Windshield assemblies incorporating the modified glass are available under part # HZA-5416.

AM-09-77/228